


Photos of Road Conditions Near Crash Site on Shoreline Highway



Disappearing fog lines, cracked pavement, and lack of shoulder characterize much of Shoreline Highway in the westbound direction. Note wider shoulder on the other side of the road.



Eastbound view of Shoreline Highway at crash scene. Note how closely the truck in the photos is to the fog line. Additionally, note how narrow the shoulder is on the Westbound lane (with truck), and how much more shoulder there is for the Eastbound lane. The yellow centerline could be moved to provide more shoulder room in the westbound lane.



Pedestrians use Shoreline Highway as a main route out of the Tamalpais Valley. Here one is seen heading eastbound. On the right side of the picture the actual crash site can be seen, with the white absorbent material and pavement stains from injuries sustained by the bicyclist right at the fog line. Note how narrow and uneven the shoulder is at this location.



Edge of pavement at crash site. Three asphalt overlays can be seen. The fog line is faintly visible to the left of the car. Note the pavement steepness and degradation in conjunction with asphalt crumbling and forming loose gravel.